

Oct 19, 1998

I purchased this 1976
Trans Am brand new
and realized its importance
to automotive history
and wanted it preserved.
As such it only has
8000 km. as of 1998
and I never drove the
car from 1980 until 1998
when it was sold to
the second owner.

Bob Huston.

4 SHERWOOD RD E
AJAX ONT

905-683-0872

P.S. to whom it may concern.

Please preserve this car as
I have done so all these
22 years of ownership.
Thanks.



General Motors of Canada Limited
Oshawa, Ontario
L1G 1K7

August, 1977

Dear Pontiac Owner:

This notice is sent to you in accordance with the requirements of the National Motor Vehicle Safety Act.

General Motors has determined that a defect which relates to motor vehicle safety exists on certain vacuum power brake equipped 1976 Pontiacs.

On these vehicles, gasoline vapor may, under certain operating conditions, condense into liquid gasoline in the power brake booster at ambient temperatures of approximately 0 degrees Fahrenheit or lower. Liquid gasoline in contact with the brake rubber diaphragm may cause deterioration in the tensile strength of the rubber to the point that the diaphragm may rupture during a brake application, resulting in loss of brake power assist which could cause vehicle crash without prior warning.

To prevent the possibility of this occurring on your vehicle, your Pontiac dealer will install a power brake vacuum hose filter. This filter will prevent gasoline vapor from entering the power brake booster from the engine vacuum source. This installation will be made at no charge to you.

Instructions for making this correction have been sent to your dealer. The time necessary to perform the labour required will be approximately 10 minutes. Prior to taking your vehicle into your dealer, we suggest you make an appointment in order to arrange a mutually agreed upon service date.

The enclosed Campaign Card identifies your vehicle. Presentation of this card to your dealer will assist their Service personnel in completing the necessary correction to your vehicle in the shortest possible time.

Further assistance, if required, may be obtained from the General Motors Zone Office nearest you. Your vehicle Owner's Manual provides the location and phone number of each respective Zone Office.

In the event you no longer own this vehicle and/or this recall modification has been performed, kindly return the enclosed Campaign Card advising particulars to General Motors of Canada Limited.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products. Your prompt co-operation would be appreciated.

Enclosure
7P07

Product Service Department,
General Motors of Canada Limited.

01

**PLEASE DO NOT STAPLE
FOLD OR MUTILATE THIS CARD**

Servicing
Dealer Code

Verification
Code

For Factory Use Only
Sequence No.

Document
Number

182352

Date Written

Dealer: Type Required Information Using These Areas To Align Form In Typewriter.

CAMPAIGN CARD - CARTE DE RAPPEL

02

Campaign
Number

Vehicle
Identification Number

Mileage

Repair
Order Number

R. O. Date
Mo. Day

Repair Codes

1

2

3

4

5

7P07

2W87W6N556255

*

*

*

*

**

Do Not Fold

**GENERAL MOTORS
OF CANADA LIMITED**



R.W. HUSTON
1968 A NOTIAN RD
PICKERING ON L1V 2G3

95374

"The signed dealer hereby certifies that he performed the above work in accordance with the terms of the 'Policies on Adjustments' section of the current General Motors of Canada Limited Service Policies and Procedures Manual' and hereby applies for credit allowed thereunder based on the information shown herein."

"I hereby request that the repair work hereinafter set forth be performed on the described motor vehicle and authorize the use of necessary labor and materials therefor. Such vehicle may be operated for test, inspection and delivery purposes."

"Je demande que le travail prescrit soit exécuté sur le véhicule automobile décrit dans la présente, et l'autorise l'utilisation du matériel et de la main-d'oeuvre nécessaire à cet effet. Tel véhicule peut être conduit pour fins de vérification, d'inspection et de livraison."


x

Customer Signature

Signature du client

Dealer Signature

Do Not Fold



BRUCE BISSELL BUICK PONTIAC LTD.

201 BAYLY STREET WEST, AJAX, ONTARIO L1S 3K3 - 416-683-6561

March 19, 1980.

Campaign No. *0C07*

Vehicle *PONTIAC*

Serial No. *2W87W6N556255*

Dear General Motors Customer:


It has been brought to our attention at Bissell Buick Pontiac that your car has a factory fault. By now you will have received a notice regarding this problem.

We would appreciate it if you would take your vehicle to your nearest Pontiac Buick dealer as they would be more than happy to repair it for you free of charge. This is a very urgent matter in that your car may be unsafe to drive.

Feel free to call me between eight and 9 Monday through Friday.

Thank you for your cooperation.

Yours truly,



I Phoned *DE: gob* *Dealer and problem is* Douglas Edwards,
Service Manager.

*EXHAUST Transducer valve which
was taken off the car in 1976. along with
the rest of the pollution Control Devices*

RLHuston



PONTIAC·BUICK·GMC MERCHANDISING

July 15, 1978

Dear Trans Am Owner:

On Saturday, August 19th and Sunday, August 20th, Pontiac has arranged for an exclusive parking area, known as the 'Trans Am Territory', for all those Trans Am drivers attending the CanAm/Trans Am race to be held at Mosport Park, on the above dates.

The Trans Am race will be held on the Saturday and the CanAm race on the Sunday.

Pontiac welcomes Trans Am drivers to join us in the 'Trans Am Territory', compare notes, talk cars and watch the racing.

A special feature of this event will be the entry in the Trans Am race of the new Herb Adams, Appliance sponsored Pontiac 'Silverbird' racer. In addition, Mr. John Schinella, Chief Designer for Firebird, will be in attendance at the 'Trans Am Territory' with a Special Type 'K' Pontiac Design Car.

The 'Trans Am Territory' will be located on the inside of corner one adjacent to the paddock. Access is through the B.F. Goodrich gate, straight ahead through the twin tunnels followed by a right turn to the 'Trans Am Territory'.

Enclosed you will find a 'Trans Am Territory' parking sticker which may be applied to the inside lower left portion of your windshield. The sticker itself is not necessary for vehicle entry to the 'Trans Am Territory' but if applied, should facilitate an easier traffic flow into the area.

To reach Mosport Park take the Liberty Street Exit off Hwy 401 at Bowmanville, and proceed north and east to the track following the signs.

This invitation is for the use of a parking area only and does NOT include gate admission. Tickets are available at the gate, or in advance through Mosport Park Ltd., 1905 Avenue Rd., Toronto (416) 781-6626.

Hope to see you there!

Yours truly,

A handwritten signature in dark ink, appearing to read 'D. Hepburn'.


D.R. Hepburn
Assistant Merchandising Manager
Pontiac Division

ENCL

T/A Z28

ENTHUSIASTS

SEE YOUR PONTIAC OR CHEVROLET DEALER SOON FOR DETAILS

ON THE  OPTION AVAILABLE

ON 1979 MODELS, OR HAVE YOUR PRESENT 1976 OR LATER TRANS-AM
OR Z28 MODIFIED DIRECTLY BY US.

OUR "ENGINEERED FOR MOTION" PACKAGES ARE WINNERS.....HANDLING
MODIFICATIONS, WEIGHT REDISTRIBUTION, AND EXHAUST MODIFICATIONS
ALL MEET FEDERAL REGULATIONS. GIVE YOUR TRANS-AM OR Z28 THE
STAGE **I** OR THE FULL STAGE **II** TREATMENT. YOU WILL NOTICE THE
DIFFERENCE.

GM OR BRAND NAME AFTERMARKET PARTS ALSO AVAILABLE AT SIGNIFICANT
SAVINGS. CALL US AT 244-6080 AND COMPARE OUR LOW, LOW PRICES.

AND NOW ON WITH THE RACES.....

GEORGE A. GOLA

MOTION ENGINEERED.

SALES DIVISION.



Ministry of
Transportation and
Communications

Robert W. Huston
6 Dingly Court
Pickering, Ont

Special Plate Office
Macdonald Block
Queen's Park
Toronto, Ontario M7A 2A2

Tel. (416) 965-3643-4

OCT 23 1979

Dear Sir or Madam:

Please be advised that the Own Choice plates numbered LUV 455 which you selected are now available, and may be obtained on receipt of the items outlined below:

1. One copy of this letter.
2. Your present Motor Vehicle Permit.
3. The enclosed JL.20 and JL.13 forms, fully completed and signed, also the Insurance Statement on back of JL.13 completed.
4. If your vehicle is new and has not been registered, we require the following items:
 - (a) Application for New Registration (JL.1) fully completed and signed.
 - (b) Certificate of Sale of New Motor Vehicle, obtained from Dealer.
 - (c) Proof of Insurance or the U.M.V.F. fee of \$150.00.
 - (d) The registration fee for the number of cylinders of the vehicle: (4 cyl. — \$30.00, 6 cyl. — \$45.00, 8 cyl. — \$60.00, 8 cyl. with over 6.5 litre engine — \$80.00).
 - (e) Form JL.20 fully completed.
 - (f) One copy of this letter.
5. (December 1 to February 28) If you wish to have your plates renewed to the current year, you may do so by forwarding the required registration fee for the number of cylinders, along with Items 1, 2 and 3, Proof of Insurance or the U.M.V.F. fee of \$150.00.
6. If your vehicle falls under Items 1, 2 and 3 the present set of regular series plates on your vehicle will have to be returned to this office for cancellation. However, in order that you may operate your vehicle, on receipt of Items 1, 2 and 3 we will forward the Own Choice Plates, but retain the vehicle permit until the regular series plates have been received for cancellation.

Yours truly,

Miss Elsie Graham,
Queen's Park Issuing.

Encl.
JL.13, JL.20

**WARRANTY
INFORMATION
ON
1976
PONTIAC
NEW CARS**

- New Car
- Emission Systems
- Tires
- Battery



Robert W. Huston

Owner's Name

1968A Notion Road

Street Address

Pickering Ont

City and State (or Province in Canada)

2W87W6N5562SS

Vehicle Identification No.

MAR 24 1976

Date of Delivery to First Retail Purchaser
(Service Date if Applicable)

31

Vehicle Mileage at Time of Such Delivery

IMPORTANT—This folder must be kept with the vehicle at all times and made available to a Pontiac Dealer if Warranty work becomes necessary. The folder should remain with the vehicle at time of resale.

Paddock
Parking

TRANS AM TERRITORY ONLY

MOSPORT PARK
Aug. 19, 20, 1978

Not Good For Gate Admission

Enter Through B.F. Goodrich Gate Only

General Motors of Canada Limited shall not be responsible for personal injuries, loss or damage, however caused, including, without limitation, theft of or damage to car or contents.



Organized by Canadian Racing Drivers Association,
Sanctioned by the Sports Car Club of America (SCCA),
Canadian Automobile Sports Club (CASC).

Erection of scaffolding or other structure prohibited. No vehicle permitted within 20 feet of fencing. The management reserves the right to revoke this license by refunding the purchase price printed hereon. Motor Racing Is Dangerous. Obey Marshals. No vehicles permitted on track. It is a condition of entry that the person holding this admission ticket/credential has read and agreed to all provisions contained on the reverse side.

NO REFUNDS. RAIN DATE TO BE ANNOUNCED.

SUNDAY
AUGUST 20, 1978

General Admission	\$9.09
Ontario Retail Sales Tax	.91
	\$10.00



RE-ADMISSION TO TRACK REQUIRES TICKET
STUB AND PASS OUT

MOSPORT



General Motors of Canada Limited

Mr. John Kavelman
31 Scott Street
Whitby, ON
L1N 3L2

November 18, 1998

Dear Mr. Kavelman:

Thank you for your request for information pertaining to your 1976 Pontiac Firebird Trans Am.


Please understand, due to the age of the material being provided, the quality may vary considerably, accuracy is based on production record information available to us. Some information may be missing, but they are as complete as we can make them.

We sincerely trust the enclosed material will be of value to you.

If you require further assistance, please feel free to contact us, toll-free, at the General Motors Customer Communication Centre, 1-800-263-3777 or 1-800-263-7854 (for bilingual service) or 1-800-263-3830 TDD (Telecommunications device for the deaf). Our centre is presently open Monday to Friday, except Statutory Holidays, from 7:30 a.m. to 11:30 p.m., Eastern Standard Time. Outside of Canada, we can be reached at (905) 644-4060 or (905) 644-3387 or by fax at (905) 644-5436, Monday to Friday, from 7:30 a.m. to 5:00 p.m., Eastern Standard Time.

We thank you for your interest.

Yours truly,


George J. Zapor
Vintage Specialist
Reference File #98073784



General Motors of Canada Limited

DATE: Nov. 18, 1998
CUSTOMER: Mr. J. Kavelman
VEHICLE: 1976 Pontiac Firebird Trans Am
VIN: 2W87W6N556255
TRIM: 19 - Black
PAINT: 13 - Sterling Silver
PRODUCTION PLANT: Norwood, OH
PRODUCTION DATE: March 9, 1976
SHIPPING DATE: March 10, 1976
MODEL NUMBER: 2FW87
ENGINE: 455 CID 200 HP V8
DEALER: Bissell Pontiac Buick Ltd.
Ajax, ON
**NUMBER PRODUCED FOR SALE IN
CANADA: (SAME MODEL NO. ONLY)** 2, 984 (471 in colour 13)

OPTION

DESCRIPTION

A01	GLASS - TINTED - ALL WINDOWS
A51	FRT BUCKET SEAT
B97	SPOILER
CAN	CANADIAN PROVISIONS
C24	WIPERS - RECESSED PARK
C41	HEATER W/DEFROSTER O/S AIR
D35	MIRRORS: LEFT REMOTE & RIGHT MANUAL CONTROL - CUSTOM SPORT
D80	AUXILIARY PANEL & VALANCE (SPOILER)
GU5	REAR AXLE - 3.23 RATIO
G80	REAR AXLE - POSITRACTION
JL2	DISC BRAKES - FRONT SINGLE PISTON
K15	LINE FUEL VAPOUR RTN
L75	ENGINE: 7.5 LITRE - 455 CID - 4 BBL
M21	4-SPEED MANUAL TRANSMISSION - CLOSE RATIO
NK3	STEERING WHEEL SPORT, SOFT RIM, SIM. LEATHER
NOD	NORWOOD, OHIO
N65	SPACE SAVER SPARE WHEEL & TIRE
P05	WHEEL HONEYCOMB



General Motors of Canada Limited

DATE: Nov. 18, 1998
CUSTOMER: Mr. J. Kavelman
VEHICLE: 1976 Pontiac Firebird Trans Am
VIN: 2W87W6N556255

<u>OPTION</u>	<u>DESCRIPTION</u>
QBX	GR70X15B STEEL BELTED BLACKWALL
WS4	OPTION TRANS AM
WW8	RALLY GAUGES
WX3	RAM AIR - SHAKER HOOD
Z49	MANDATORY CANADIAN BASE EQUIP MODIFICATIONS
W84	ADDITIONAL FUEL FOR DELIVERY

Documented by George Zapora